



**Carrie T. Dunton**  
Director, Nuclear Site Support  
Oconee Nuclear Station

**Duke Energy**  
ON01VP | 7800 Rochester Hwy  
Seneca, SC 29672

o. 864.873.3477  
f. 864.873.4208  
carrie.dunton@duke-energy.com

ONS-2017-064

September 20, 2017

10 CFR 50.73

Attn: Document Control Desk  
U. S. Nuclear Regulatory Commission  
11555 Rockville Pike  
Rockville, MD 20852-2746

Duke Energy Carolinas, LLC  
Oconee Nuclear Station, Unit 3  
Docket Number: 50-287  
Renewed Operating License DPR-55

Subject: Licensee Event Report 287/2017-001, Revision 0 - Unit 3 Reactor Protection System  
Actuation - Reactor Trip Due to Turbine Trip from Generator Lockout

Licensee Event Report 287/2017-001, Revision 0, is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv)(A) to provide a report of the subject event.

There are no regulatory commitments associated with this LER.

If there are questions, or further information is needed, contact David Haile, in Oconee Regulatory Affairs, at (864) 873-4742.

Sincerely,

Carrie T. Dunton  
Director, Nuclear Site Support  
Oconee Nuclear Station

Enclosure: Licensee Event Report 287/2017-001, Revision 0 - Unit 3 Reactor Protection System  
Actuation - Reactor Trip Due to Turbine Trip from Generator Lockout.

IEZZ  
NRR

ONS-2017-064  
September 20, 2017  
Page 2

cc :

Ms. Catherine Haney, Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Marquis One Tower  
245 Peachtree Center Ave., NE, Suite 1200  
Atlanta, GA 30303-1257

Ms. Audrey L. Klett, Project Manager  
(by electronic mail only)  
U.S. Nuclear Regulatory Commission  
11555 Rockville Pike  
Mail Stop O-08B1A  
Rockville, MD 20852-2738

Mr. Eddy Crowe  
NRC Senior Resident Inspector  
Oconee Nuclear Station

INPO (Word File via E-mail)



## LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of  
digits/characters for each block)(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

APPROVED BY OMB: NO. 3150-0104

EXPIRES: 03/31/2020

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Information Services Branch (T-2 F43), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Oconee Nuclear Station Unit 3					2. DOCKET NUMBER 5000287					3. PAGE 1 of 3		
4. TITLE Unit 3 Reactor Protection System Actuation - Reactor Trip due to Turbine Trip from Generator Lockout												
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME NA		DOCKET NUMBER 5000	
07	24	2017	2017 - 001 - 00			09	20	2017	FACILITY NAME NA		DOCKET NUMBER 5000	
9. OPERATING MODE			11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
Mode 1			<input type="checkbox"/> 20.2201(b)			<input type="checkbox"/> 20.2203(a)(3)(I)			<input type="checkbox"/> 50.73(a)(2)(II)(A)		<input type="checkbox"/> 50.73(a)(2)(VIII)(A)	
			<input type="checkbox"/> 20.2201(d)			<input type="checkbox"/> 20.2203(a)(3)(II)			<input type="checkbox"/> 50.73(a)(2)(II)(B)		<input type="checkbox"/> 50.73(a)(2)(VIII)(B)	
			<input type="checkbox"/> 20.2203(a)(1)			<input type="checkbox"/> 20.2203(a)(4)			<input type="checkbox"/> 50.73(a)(2)(III)		<input type="checkbox"/> 50.73(a)(2)(IX)(A)	
			<input type="checkbox"/> 20.2203(a)(2)(I)			<input type="checkbox"/> 50.36(c)(1)(I)(A)			<input checked="" type="checkbox"/> 50.73(a)(2)(IV)(A)		<input type="checkbox"/> 50.73(a)(2)(X)	
10. POWER LEVEL  100%			<input type="checkbox"/> 20.2203(a)(2)(II)			<input type="checkbox"/> 50.36(c)(1)(II)(A)			<input type="checkbox"/> 50.73(a)(2)(V)(A)		<input type="checkbox"/> 73.71(a)(4)	
			<input type="checkbox"/> 20.2203(a)(2)(III)			<input type="checkbox"/> 50.36(c)(2)			<input type="checkbox"/> 50.73(a)(2)(V)(B)		<input type="checkbox"/> 73.71(a)(5)	
			<input type="checkbox"/> 20.2203(a)(2)(IV)			<input type="checkbox"/> 50.46(a)(3)(II)			<input type="checkbox"/> 50.73(a)(2)(V)(C)		<input type="checkbox"/> 73.77(a)(1)	
			<input type="checkbox"/> 20.2203(a)(2)(V)			<input type="checkbox"/> 50.73(a)(2)(I)(A)			<input type="checkbox"/> 50.73(a)(2)(V)(D)		<input type="checkbox"/> 73.77(a)(2)(I)	
			<input type="checkbox"/> 20.2203(a)(2)(VI)			<input type="checkbox"/> 50.73(a)(2)(I)(B)			<input type="checkbox"/> 50.73(a)(2)(VII)		<input type="checkbox"/> 73.77(a)(2)(II)	
			<input type="checkbox"/> 50.73(a)(2)(I)(C)			<input type="checkbox"/> OTHER			Specify in Abstract below or in NRC Form 366A			
12. LICENSEE CONTACT FOR THIS LER												
LICENSEE CONTACT David Haile, Oconee Regulatory Affairs								TELEPHONE NUMBER (Include Area Code) 864-873-4742				
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT												
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX			
NA					NA							
14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. Expected Submission Date) <input checked="" type="checkbox"/> NO								15. EXPECTED SUBMISSION DATE		MONTH	DAY	YEAR
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)												
<p>On 7/24/17, with Oconee Nuclear Station (ONS) Unit 3 operating at 100 percent power, Transmission Department Relay personnel were in the ONS 525kV Switchyard Relay House performing preventive maintenance on a Breaker Failure Relaying device for Power Circuit Breaker PCB-57. This is a non-safety PCB that isolates a commercial transmission line from the commercial bus in the 525kV switchyard. The maintenance was intended to actuate the protective relaying for PCB-57. The crew inadvertently connected test equipment to the adjacent relaying for PCB-58. The activation of the PCB-58 relay resulted in a Unit 3 separation from the electrical grid and a generator "Lockout." The lockout generates a turbine trip which in turn trips the reactor via the Reactor Protection System (RPS). This actuation of the RPS is reportable per 10 CFR 50.73(a)(2)(iv)(A).</p> <p>Post trip plant response was normal and plant conditions were controlled and maintained within the allowances of Technical Specifications with no personnel injuries or safety system actuations.</p> <p>A cause analysis attributed the cause of this event to human error in that test equipment was inadvertently connected to relaying for the incorrect PCB. The cause analysis corrective actions will address the likelihood of comparable human errors from occurring.</p>												



# **LICENSEE EVENT REPORT (LER) CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER		
Oconee Nuclear Station Unit 3	5000287	YEAR	SEQUENTIAL NUMBER	REV NO.
		2017	- 001	- 00

## *Narrative*

### EVALUATION:

#### BACKGROUND

The sketch on the right depicts the 525kV power circuit breaker (PCB) arrangement.

The Red Bus[EA] and the Yellow Bus[EA] are commercial, non-safety buses.

Transmission crews are not part of the nuclear plant's staff, but are responsible for performing work in the 525kV switchyard[FK]. The coordination, planning, and execution of Transmission work activities are controlled by several approved processes which establish communication and approval protocols between the Nuclear and Transmission organizations.

#### EVENT DESCRIPTION

On 7/24/17, with ONS Unit 3 operating at 100% power, Transmission Department Relay personnel in the ONS Switchyard Relay House were performing preventive maintenance on a relay device associated with PCB-57. This is a non-Unit PCB that isolates a commercial transmission line from the Red Bus in the 525kV switchyard.

The maintenance procedure first opens and isolates PCB-57, then triggers the protective relaying while ensuring that the PCB trip function actuates properly. In this case the Transmission crew inadvertently connected the test equipment to the incorrect relay device (several identical relay devices are mounted in one cabinet but actuate separate PCBs). The crew connected test equipment to the adjacent relay device for PCB-58 instead of the relay device for PCB-57. PCB-58 is a Unit breaker that connects the Unit 3 generator output[EL] to the switchyard buses. Activating a test signal on the PCB-58 relay device resulted in Unit 3 generator "lockout" and a loss of electrical load by tripping open PCB-58 and PCB-59. The lockout generates a turbine trip which in turn trips the reactor via the Reactor Protection System (RPS)[JC].

The reactor trip was uncomplicated, with all systems responding normally.


#### CAUSAL FACTORS

One cause is attributed to a lack of rigor by the Transmission technicians in utilizing appropriate Human Performance tools to ensure their actions were performed on the intended component.

A second cause is attributed to a lack of coordination between the Transmission and Nuclear organizations for implementation of interface processes regarding the risk of work performed in close proximity of the PCB-58 relay device.

Transmission personnel are accountable for the use of human performance tools to ensure component identification is correct and maintained during maintenance. These tools include component markers and physical barriers to ensure maintenance is only performed on the assigned component. These types of tools were not adequately applied during performance of this task.

The interface guidelines call for Transmission to have work plan communications with the appropriate nuclear site groups so a risk assessment for the need of nuclear site oversight can be made. A breakdown in this communication led to a misunderstanding of the risk associated with this work (close



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See form 366 above for burden estimate)

1. FACILITY NAME	2. DOCKET NUMBER	6. LER NUMBER		
Oconee Nuclear Station Unit 3	5000287	YEAR	SEQUENTIAL NUMBER	REV NO.
		2017	- 001	- 00

***Narrative***

proximity to the PCB-58 relay device) and thus the coordination and oversight of this work was inadequate.

**CORRECTIVE ACTIONS**

This event was entered into the Corrective Action Program (NCR 02138958) which included a cause analysis. The cause analysis corrective actions are summarized as follows:

- In order to improve the application of human performance rigor and the recognition of operational risks when working in the switchyard relay cabinets;
  1. Training, applicable to this event, will be provided to the necessary groups,
  2. Cabinet/relay labeling will be enhanced, and
  3. Interface guidance applicable to this event will be improved.
- The site work planning and approval processes will be improved for work within the site switchyards that require coordination with the Transmission department.

**SAFETY ANALYSIS**

Loss of electrical load from 100 percent power is an analyzed event described in the ONS Updated Final Safety Analysis Report, Section 15.8. All onsite safe shutdown equipment performed as required with no complications. Therefore this event did not present a risk to the health and safety of the plant or the public.

**ADDITIONAL INFORMATION**

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX].

**Similar Events:**

None